

Oglesby Towers
6700 South Oglesby
Chicago, Illinois



Mueller & Associates, LLC (MA) performed concrete & masonry restoration of the east and north facades. MA tested windows to determine the different causes for the water infiltration and provided ownership with a frame modification to prevent expensive window system replacements.

M&A provided the following services:

- Critical Facade Inspection
- Construction document preparation in the form of drawings, specifications and bid table
- Facade restoration of the north, east and west elevations.
- Water testing of the window assemblies

